

Work Order ID 150213

Wednesday, August 24, 2016 11:27:35 AM

150213

Page 1

Item ID: D412-711-021 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Vertical Reference Door Modification LH
 Start Date: 8/10/2016 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 8/24/2016 Req'd Qty: 1.00 *1* Customer:
 Reference:

Approvals: Process Plan: DAS 21 Date: AUG 25 2016 Tooling: _____ Date: _____ Run Start *NR1*
 QC: 9-89 Date: _____ SPC (Y/N): _____ Date: _____ Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D412-711	K								
100	Document Control	0.00							
100	DOCUMENT CONTROL								
DC	Memo	0.00							
Doc.Control -USB or Paperwork	Photocopy bluefiles and create labels per PPP D412-711-021 CHG002								
120	Pick Kit	0.00							
120	Purchasing								
Packaging	Memo	0.00							
Packaging									
130	QC4- 100% Inspect kits for completeness	0.00							
130									
QC	Memo	0.00							
Quality Control									

10/11

NOV 09 2016

DAS 6 9-89

DAS 21 9-89

10-11-10

DAS 27 9-89

DAS 28 9-89

DAS 6 9-89

NOV 09 2016

DAS 27 9-89

NOV 11 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : _____							

Work Order ID 150213

Wednesday, August 24, 2016 11:27:35 AM

150213

Page 2

Item ID: D412-711-021

Accept

N900040100

Setup Start

NS1

Revision ID:

Item Name: Vertical Reference Door Modification LH

Stop

NS2

Start Date: 8/10/2016 Start Qty: 1.00

1

Cust Item ID:

Required Date: 8/24/2016 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals:

Process Plan: _____

Date: _____

Tooling: _____

Date: _____

Run Start

NR1

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

150

0.00

150

Packaging

Memo

0.00

Identify and pack for shipping as per PPP D412-711-021

Location: _____

PPP rev: _____

sold

DAS

27

9-89

NOV 11 2016

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.02

DAS

21

9-89

NOV 11 2016

Quality Control

DAS

21

9-89

NOV 11 2016

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
3 16 32									
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
OTHER : ☐									

Picklist Print

Wednesday, August 24, 2016 11:27:34 AM

Page 1

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:A 11.04.07 new issue DD verf:EC
14.04.25 ECN14-548 DD verf:JLM

IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D4324-011		Manufactured	No				Each	2.0000		1			
D4324-011									**				
Armrest Assembly													

DAS
27
9-89

Location	Loc Qty	Loc Code
ST459	2	
145819	1	
146872	1	

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

D412-761-043		Manufactured	No			120	Each	5.0000	1	1			
D412-761-043									**				
Modified Latch Mechanism, LH													

DAS
27
9-89

Location	Loc Qty	Loc Code
FG020	5	
144456	5	

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

D412-711-101		Manufactured	No			120	Each	3.0000	1	1			
D412-711-101									**				
Replacement Vertical Reference Window													

DAS
27
9-89

Location	Loc Qty	Loc Code
FG099	3	
147654	3	

DAS
6
9-89

DAS
28
9-89

D3802-1-120		Manufactured	No			120	Each	6.0000	1	1			
D3802-1-120									**				
Window Seal - 120"													

DAS
27
9-89

Location	Loc Qty	Loc Code
ST639	6	
146052	1	
146553	5	

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Description Work Order Deviation		Disposition			
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Set-up ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
		OTHER : _____			

Picklist Print

Wednesday, August 24, 2016 11:27:34 AM

Page 2

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

D4165-1 Manufactured No 120 Each 2.0000 1 1

D4165-1

Doubler

**

NOV 0 9 2016

DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

ST236

2

143350

2

D4165-3

Manufactured No

120 Each

3.0000

1

1

D4165-3

Inner Door Panel

**

NOV 0 9 2016

DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

st238

3

141941

3

D4165-5

Manufactured No

120 Each

2.0000

1

1

D4165-5

Aft Rib

**

NOV 0 9 2016

DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

ST236

2

143362

2

D4165-7

Manufactured No

120 Each

6.0000

1

1

D4165-7

Fwd Rib

**

NOV 0 9 2016

DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

ST236

6

116604

6

D4165-9

Manufactured No

120 Each

2.0000

1

1

D4165-9

Angle

**

NOV 0 9 2016

DAS 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

ST237

2

146915

2

Wednesday, August 24, 2016 11:27:34 AM

Shop Packet Print

Page 2

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER :							

Picklist Print

Wednesday, August 24, 2016 11:27:34 AM

Page 3

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

D4165-11	Manufactured	No	120	Each	3.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
D4165-11										
Door Cover Panel										
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>					
			st238	3						
			141938	3						
D4207-1	Manufactured	No	120	Each	3.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
D4207-1										
Window Retainer										
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>					
			ST237	3						
			141942	3						
D4207-3	Manufactured	No	120	Each	4.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
D4207-3										
Instrument Window										
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>					
			ST237	4						
			147147	4						
D4269-1	Manufactured	No	120	Each	7.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
D4269-1										
Angle										
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>					
			ST089	7						
			143364	7						
D4269-3	Manufactured	No	120	Each	3.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
D4269-3										
Angle										
			<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>					
			ST089	3						
			141939	3						

Wednesday, August 24, 2016 11:27:35 AM

Shop Packet Print

Page 3

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval		
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY							
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐				
Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐				
Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐				
Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐				
Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐				
Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐				
Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐				
Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐				
LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐				
Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐				
Past Expiry Date ☐	Manufacturing Process ☐								
Misidentified ☐	Past Due ☐	OTHER :							

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 4

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

D4269-5 Manufactured No 120 Each 2.0000 1 1

D4269-5

Angle

**

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

2

143365

2

D4269-7

Manufactured No

120 Each

0.0000

1

1

D4269-7

Angle

**

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

D4327-1

Manufactured No

120 Each

3.0000

1

1

D4327-1

Angle

**

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

3

141940

3

D4327-3

Manufactured No

120 Each

3.0000

1

1

D4327-3

Angle

**

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST237

3

141943

3

D4385-1

Manufactured No

120 Each

7.0000

2

2

D4385-1

Placard

**

NOV 09 2016

DAS
6
9-89

DAS
28
9-89

Location

Loc Qty

Loc Code

ST095

7

144020

1

147080

6

6/13/2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : _____					

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 5

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

AN3-3A	Purchased	No	120	Each	196.0000	22	22
--------	-----------	----	-----	------	----------	----	----

AN3-3A

Bolt

**

NOV 09 2016

DAS 28 9-89

DAS 27 9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST350	196	
m134738	24	
m135274	22	
m135408	50	
m135466	100	

AN3-4A	Purchased	No	120	Each	197.0000	20	20
--------	-----------	----	-----	------	----------	----	----

AN3-4A

Bolt

**

13570 NOV 09 2016

DAS 28 9-89

DAS 27 9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST350	197	
m134955	197	

AN3-6A	Purchased	No	120	Each	207.0000	26	26
--------	-----------	----	-----	------	----------	----	----

AN3-6A

Bolt

**

NOV 09 2016

DAS 28 9-89

DAS 27 9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST349	207	
M134955	207	

AN3-12A	Purchased	No	120	Each	32.0000	1	1
---------	-----------	----	-----	------	---------	---	---

AN3-12A

Bolt

**

135703

NOV 09 2016

DAS 28 9-89

DAS 27 9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
ST349	32	
m133064	16	
m134257	16	

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					

Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐				FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
				OTHER : ☐							

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 6

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

NAS1149F0332P

Purchased

No

120

Each

1,441.000

92

92

NAS1149F0332P

Washer

**

135544

NOV 09 2016

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

GA

282

m133709

282

ST262

1159

m134257

37

m134676

19

m135058

1103

CR3242-4-2

Purchased

No

120

Each

185.0000

34

34

CR3242-4-2

RIVET

**

NOV 09 2016

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

ST318

185

m134500

1

m134962

184

MS20426AD3-3

Purchased

No

120

Each

6,580.000

135

135

MS20426AD3-3

RIVET

**

131624x36

NOV 09 2016

DAS 28
6 9-89

DAS 27
9-89

Location

Loc Qty

Loc Code

fg108

400

M135354

400

GA

44

M131624

44

ST312

6136

M135274

6136

99

Wednesday, August 24, 2016 11:27:35 AM

Shop Packet Print

Page 6

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date: _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval		
Description Work Order Deviation				Disposition					
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐							
		OTHER : ☐							

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 7

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS20426AD4-3

Purchased

No

120

Each

1,431.000

140

140

MS20426AD4-3

Rivet

**

NOV 09 2016

DAS 8 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

GA

1171

113064

171

m125807

1000

ST312

260

m125807

260

140

MS20470AD3-3

Purchased

No

120

Each

6,222.000

25

25

MS20470AD3-3

RIVET, UNIVERSAL HEAD

**

NOV 09 2016

DAS 8 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

GA

877

1065

877

ST310

5345

16941

5345

25

MS20470AD4-3

Purchased

No

120

Each

331.0000

90

90

MS20470AD4-3

Rivet, Universal Head

**

NOV 09 2016

M1355310 X43

DAS 8 28 9-89

DAS 27 9-89

Location

Loc Qty

Loc Code

GA

284

2193

284

ST310

47

2193

47

47

Wednesday, August 24, 2016 11:27:35 AM

Shop Packet Print

Page 7

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval																																																										
Description Work Order Deviation				Disposition				Completed By _____ Lead hand / Supervisor Approval Verification _____ QC / QA Coordinator Approval _____																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER : _____			
Misidentified ☐	Past Due ☐																																																																

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 8

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

120

Each

1,576.000

24

24

MS21042L3

Nut

**

135530

NOV 09 2016

DAS 8 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

FP001

14

m133790

14

GA

531

m134360

112

m135135

419

ST303

1031

m134039

12

m135056

7

m135135

412

m135407

600

MS21059L3

Purchased

No

120

Each

122.0000

4

4

MS21059L3

Nut Plate

**

M135704

NOV 09 2016

DAS 8 28
9-89 9-89

DAS
27
9-89

Location

Loc Qty

Loc Code

CA

8

M129682

8

GA

16

M135058

16

ST301

78

M135015

10

M135297

68

ST303

20

M133016

20

Wednesday, August 24, 2016 11:27:35 AM

Shop Packet Print

Page 8

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date : _____		Step #: _____		QTY Effective : _____			MRB (QSI042) Approval 		
Description Work Order Deviation				Disposition					
							Completed By _____		
							Lead hand / Supervisor Approval Verification _____		
							QC / QA Coordinator Approval _____		

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER : _____						
Misidentified	☐	Past Due	☐							

Picklist Print

Wednesday, August 24, 2016 11:27:35 AM

Page 9

Work Order ID: 150213

150213

Parent Item: D412-711-021

D412-711-021

Parent Item Name: Vertical Reference Door Modification LH

Start Date: 8/10/2016

Required Date: 8/24/2016

Start Qty: 1.00

Required Qty: 1.00

MS21069L3	Purchased	No	120	Each	77.0000	34	34	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
MS21069L3										
ANCHOR NUT										

DAS
27
9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

ST299	77	
m134955	77	

MS21069L08	Purchased	No	120	Each	542.0000	8	8	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
MS21069L08										
ANCHOR NUT										

DAS
27
9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

ST299	542	
123522	542	

MS21071L3	Purchased	No	120	Each	130.0000	3	3	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
MS21071L3										
ANCHOR NUT										

DAS
27
9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

S299	100	
125654	100	
ST299	30	
m129702	30	

MS21071L08	Purchased	No	120	Each	153.0000	1	1	NOV 09 2016	DAS 6 9-89	DAS 28 9-89
MS21071L08										
ANCHOR NUT										

DAS
27
9-89

<u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
-----------------	----------------	-----------------

ST299	153	
102587	53	
103447	100	

Wednesday, August 24, 2016 11:27:35 AM

Shop Packet Print

Page 9

DQA: _____ Date: _____

WORK ORDER NON-CONFORMANCE / UPDATE



QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

REFERENCE ONLY

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	QTY -043	PART NUMBER	DESCRIPTION
X								D412-711-011	VERTICAL REFERENCE DOOR INSTALLATION, 212/412
	X							D205-711-013	VERTICAL REFERENCE DOOR INSTALLATION, 205/210
		X						D204-711-015	VERTICAL REFERENCE DOOR INSTALLATION, 204
			X					D214-711-017	VERTICAL REFERENCE DOOR INSTALLATION, 214
				X				D212-711-019	VERTICAL REFERENCE DOOR EAGLE SINGLE
					X			D412-711-021	VERTICAL REFERENCE DOOR KIT
A1	A1	A1	A1	A1		X		D412-711-041	VERTICAL REFERENCE DOOR ASSEMBLY
							X	D412-711-043	SNAP VENT KIT
					1	1		D412-761-043	MODIFIED LATCH MECHANISM KIT, LH (REPLACES EA20469-23/-24/-25)
					1	1		D412-711-101	REPLACEMENT WINDOW (REPLACES EAGLE P/N EB212-100L / EA20469-3)
					1	1		D3802-1-120	RUBBER STRIP
							2	D3932-1	SNAP VENT
					1	1		D4165-1	DOUBLER
					1	1		D4165-3	DOOR INNER SKIN (REPLACES EA20469-18)
					1	1		* D4165-5	AFT RIB (REPLACES EA20469-34)
					1	1		** D4165-7	FWD RIB (REPLACES EA20469-31)
					1	1		D4165-9	ANGLE (REPLACES EA20469-17)
					1	1		D4165-11	DOOR COVER PANEL (REPLACES EA20469-21)
					1	1		D4207-1	WINDOW RETAINER (REPLACES EA20469 -14)
					1	1		D4207-3	WINDOW (REPLACES EA20469-13)
					1	1		* D4269-1	ANGLE (REPLACES EA20469-33)
					1	1		** D4269-3	ANGLE (REPLACES EA20469-30)
					1	1		** D4269-5	ANGLE (REPLACES EA20469-29)
					1	1		* D4269-7	ANGLE (REPLACES EA20469-32)
					1	1		D4324-011	ARM REST ASSEMBLY (REPLACES EA20469-16)
					1	1		D4327-1	ANGLE (REPLACES EA20469-11)
					1	1		D4327-3	ANGLE (REPLACES EA20469-07)
					2	2		D4385-1	PLACARD

K

K

* PART OF EA20469-10 REAR RIB ASSEMBLY

** PART OF EA20469-12 FWD RIB ASSEMBLY

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 2 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

QTY -011	QTY -013	QTY -015	QTY -017	QTY -019	QTY -021	QTY -041	PART NUMBER	DESCRIPTION
					22	22	AN3-3A	BOLT
					20	20	AN3-4A	BOLT
					26	26	AN3-6A	BOLT
					1	1	AN3-12A	BOLT
					92	92	NAS1149F0332P	WASHER (OR AN960-10L)
					34	34	CR3242-4-2	RIVET
					135	135	MS20426AD3-3	RIVET
					140	140	MS20426AD4-3	RIVET
					25	25	MS20470AD3-3	RIVET
					90	90	MS20470AD4-3	RIVET
					24	24	MS21042L3	NUT
					4	4	MS21059L3	NUT PLATE
					34	34	MS21069L3	NUT PLATE
					8	8	MS21069L08	NUT PLATE
					3	3	MS21071L3	NUT PLATE
					1	1	MS21071L08	NUT PLATE
						1	204-030-853-125	LH COPILOT DOOR (204-030-853-137/-155)
1							D412-711-111	WIRING HARNESS, 212/412
B ₁							B ₁ D4268-043	INSTRUMENT PANEL, 212/412 (REPLACES EA20469-15-412)
	1						D205-711-113	WIRING HARNESS, 205
	B ₁						B ₁ D4268-041	INSTRUMENT PANEL, 205 (REPLACES EA20469-15-205)
		1					D204-711-115	WIRING HARNESS, 204
		B ₁					B ₁ EA20469-15-204	INSTRUMENT PANEL, 204
			1				D214-711-117	WIRING HARNESS, 214
			B ₁				B ₁ EA20469-15-214	INSTRUMENT PANEL, 214
				1			D212-711-119	WIRING HARNESS, EAGLE SINGLE
				B ₁			B ₁ D4268-047	INSTRUMENT PANEL, EAGLE SINGLE

(A) IF CUSTOMER PREFERS TO SUPPLY AND MODIFY THEIR OWN DOOR, D412-711-021 SHOULD BE SUPPLIED IN LIEU OF D412-711-041.
(B) INSTRUMENT PANEL INCLUDED WITH HARNESS ABOVE

NOTES

1) WIRING HARNESSES:

For Bell 204/205/210/214 Wiring Harnesses, use drawing D2046904.
For Bell 212 Wiring Harnesses, use drawing D2046903*.
For Bell 412 Wiring Harnesses, use drawing D412-711-901.
For Bell 212 modified per SH07-28/SR02831NY use D212-761-224 or D212-761-225 depending on aircraft s/n.
* Despite the note on the drawing, D2046903 is applicable to all 212 aircraft serial numbers

Wiring Harnesses will vary depending on aircraft s/n.

2) D412-711-101 REPLACEMENT WINDOW:

To increase downward viewing clarity, it is acceptable to cut a small section from the replacement window on its downward side per Figure 1 of this document. The cutout can be a maximum of 9.00" wide x 17.00" long (229mm x 432mm), measured along the profile of the replacement window. The corners of the cutout must have a minimum radius of 2" (50mm). The cutout should be located at least 1.0" (25mm) from the flange. The actual shape of the cutout can vary as desired, as long as the overall dimensions are within the specified limits. See Figure 1 for reference.

3) D412-711-043 SNAP VENT KIT:

It is acceptable to install a total of up to 2X D3932-1 Snap Vents (available from Dart) onto the D412-711-101 Replacement Window to provide ventilation into the cabin. Refer to Figure 1 for acceptable locations and size of cutouts.

4) It is acceptable to use MS21042L3 nuts to install the window in lieu of anchor nuts shown on D2046901.

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	DC	DRAWING NO.	REV. K
MFG. APPR.	JLM	D412-711	SHEET 3 OF 6
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	VERTICAL REFERENCE DOOR	NTS
DATE	14.04.07	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	